



Date: 30.04.2023

TO WHOMSOEVER IT MAY CONCERN

This is regarding Structural Health Safety Audit of Cascades Tower-10 at Plot No. AA-III/BLK-1, Action area-III, New Town, Rajarhat, Kolkata.

The structural health of Cascades Tower-10 has been audited and found safe as per National Building Code and relevant BIS Codes. However the measures of strengthening / repair to be implemented are as follows.

- Voids, honeycomb concrete and exposed reinforcements are noticed at various locations of the Tower as mentioned in the report. These areas are to be repaired with single pack polymer modified mortar/ micro-concrete and pressure grouting with low viscous epoxy compound.
- Flexural and shear cracks are noticed in beams at many locations. These beams are to be strengthened with carbon fibre wrapping as mentioned in the report.
- Cracks are noticed at soffit level of slabs at different floors. These cracks are to be sealed by pressure grouting with low viscous epoxy compound.
- Pointing with 1:4 cement sand mortar is to be carried out at mortar joints of the brick mortar.

A handwritten signature in blue ink, appearing to read 'Subhajit Saraswati'.

Dr. Subhajit Saraswati
Professor
Department of Construction Engineering
Jadavpur University